


Unikanie pola rażenia

Hierarchia środków kontroli ryzyka pokazuje, które środki zapobiegawcze są najskuteczniejsze




Unikanie pola rażenia


1. Moving vehicles and mobile equipment




2. Mechanical lifting and hoisting




3. Work at height, falls and dropped objects




4. Tensioned lines, spring loaded devices and stored energy




5. Uncontrolled rolling, sliding or falling




6. Pressurized systems and vacuum systems



7. Machinery and tools



8. Electrical equipment and exposure



9. Projectiles, explosion and jet fire



10. Natural environmental events and extreme weather

